

46

7/15/94
ual/FY93 Rev
riett / Tony
JWA

81194

City: DAVENPORT

R00307891
RCRA RECORDS CENTER

Answer key for next three questions:

1. Is there any known or suspected groundwater contamination ON SITE? 0
2. Is there any OFF SITE migration or downgradient exposure for surface or groundwater? 0
3. Is there any other known or suspected release to soil/air/surface water from SWMU(s) or regulated unit(s)? 0

Answer key for following question:

- 1 = clay, compact till, m shale, unfractured metamorphic and igneous rock
2 = silt, loess, silty clays, silty loams, less permeable limestone, dolomites and sandstone
3 = fine and silty sand, sandy loams, loamy sands, moderately permeable limestone, dolomite, sandstone (no karst), moderately fractured igneous and metamorphic rock, some coarse till
4 = gravel, sand, highly fractured igneous and metamorphic rocks

4. Hydrogeologic vulnerability of site: 4

 Yes No

Rev
[Signature]

7/18/94

slay by HLJ
slay by DPict

